







BILLY




BOX 1/4

②	1625 x 970 x 120	x1
④	1725 x 300 x 55	x1
⑮	500 x 25 x 3	x1
⑯	2060 x 1570 x 0.5	x1




BOX 2/4

①	2010 x 300 x 55	x1
③	2010 x 300 x 55	x1




BOX 3/4


No	↗	↖	↗	PCS
⑫	775	53	8	x32
⑪	1434	60	20	x1
⑩	1950	60	52	x1
⑨	1494	60	80	x2
⑧	1950	73	60	x2
⑬	150	40	35	x2
⑫	185	40	35	x6
⑤	1515	40	35	x1



BOX 4/4




G x 2



6,3 x 50

50mm


B x 4



3,5 x 45

45mm


C x 32



M6 x 20

20mm


D x 6



M6 x 30

30mm


E x 16




M6 x 60

60mm


I x 4




K x 4




L x 4




J x 4



Ox10




G x 16



7,0 x 70

70mm


M x 1



M8 x 40

40mm


F x 4




M8x14

14mm

N x 1




Z x 1




4 x 60

Y x 1



5 x 80


H x 6




5.0x30

30mm


O





P





Hx2







1




2







4




5




6




7







8






9





10



11





12





13


O x 10












14



15









18



12h 20°C



H x 2



F x 4

