








BILLY 1800




BOX 1/4

②	1925 x 970 x 120	x1
④	1925 x 300 x 55	x1
⑮	500 x 25 x 3	x1
⑯	2060 x 1870 x 0.5	x1




BOX 2/4

①	2010 x 300 x 55	x1
③	2010 x 300 x 55	x1




BOX 3/4


No	↗	↖	↗	PCS
⑫	875	53	8	x32
⑪	1734	60	20	x1
⑩	1950	60	52	x1
⑨	1794	60	80	x2
⑧	1950	73	60	x2
⑬	150	40	35	x2
⑫	185	40	35	x6
⑤	1815	40	35	x1



BOX 4/4




G x 2



50mm

6,3 x 50


B x 4



45mm

3,5 x 45


C x 32



20mm

M6 x 20


D x 6



30mm

M6 x 30


E x 16




60mm

M6 x 60


I x 4




K x 4




L x 4




J x 4



Ox10




G x 16



70mm

7,0 x 70

F x 4




14mm

M8x14




N x 1

Z x 1




4 x 60

Y x 1



5 x 80


H x 6




30mm

5.0x30


O





P






Hx2








1




2




3




4




5




6




7







8






9





10



11





12





13


O x 10







14




15









D x 6




M6 x 30




18



12h 20°C



H x 2



F x 4

